




HOLE IN CHASSIS $\varnothing 4.8\text{mm}$
CHASSIS MAX THICKNESS 1.8mm

NOTE:1. SHRINKING IS NORMAL STATUS.
內縮為正常現象.
2. MADE OF EQUIVALENT MATERIAL.
可使用同等材質.



康揚企業股份有限公司
KANG YANG HARDWARE ENTERPRISE CO., LTD.
康揚塑膠(東莞)有限公司
KANG YANG PLASTIC(DONG GUAN)CO.,LTD.
康哲電腦配件(吳江)有限公司
KANG CHE COMPUTER COMPONENTS(WUJIANG)CO.,LTD.

PROPRIETARY AND CONFIDENTIAL THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF KANG YANG HARDWARE ENTERPRISE CO. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF KANG YANG HARDWARE ENTERPRISE CO. IS PROHIBITED.	DATE	2007.02.01		TITLE	WIRE MOUNT		DWG. NO.		PART NO.	
	DRAWN	FRANK		MATERIAL	NYLON 66 UL94V-2		CHY-1		CHY-1	
	CHECKED	彭永康		COLOR	NATURAL	FINISH	SIZE	SPEC. DWG.		REV
	APPROVED	Kang		UNLESS OTHERWISE SPECIFIED TOLERANCE: SEE ABOVE		A4			A	
	DO NOT SCALE DRAWING					SCALE: 3:1	UNIT	mm	SHEET 1 OF 1	