



CHASSIS MOUNTING HOLE $\phi 4.1$ mm
 CHASSIS THICKNESS 1.0 mm

FANS MOUNTING HOLE $\phi 3.5$ mm
 FANS THICKNESS 5.2 mm

- NOTE: 1. SHRINKING IS NORMAL STATUS.
 內縮為正常現象。
2. MADE OF EQUIVALENT MATERIAL.
 均可使用同等材質。
3. THE COLOR BATCH TEST REPORT IS ONLY FOR FIRST LOT TEST.
 色母環保檢測報告, 僅提供原始測試報告。

K
 ISO 9001
 ISO 14001
 QC 080000
 IATF 16949

康揚企業股份有限公司
 KANG YANG HARDWARE ENTERPRISE CO., LTD.
 康揚塑膠(東莞)有限公司
 KANG YANG PLASTIC(DONG GUAN)CO.,LTD.
 康哲電腦配件(吳江)有限公司
 KANG CHE COMPUTER COMPONENTS(WUJIANG)CO.,LTD.

PROPRIETARY AND CONFIDENTIAL THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF KANG YANG HARDWARE ENTERPRISE CO. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF KANG YANG HARDWARE ENTERPRISE CO. IS PROHIBITED. DO NOT SCALE DRAWING	DATE	TITLE		DWG. NO.	PART NO.	
	2022.09.07	FAN FRAME		FANCA-2VB	FANCA-2VB	
	DRAWN	MATERIAL			SIZE	SPEC. DWG
	Y.C.P	TPE UL94V-0		A4		
CHECKED	COLOR	FINISH	SCALE: 1:1		UNIT	SHEET 1 OF 1
李柏育	BLACK		mm			
APPROVED	UNLESS OTHERWISE SPECIFIED TOLERANCE:		SEE ABOVE			
Kang						