



MOUNTING HOLE  $\phi 7$   
CHASSIS THICKNESS 3.2~3.8

新公差

NOTE:N